EXH	IBIT_	7		
DAT	F	1	30	07
HB_	374			4
	The state of the s	and the same of	The state of the state of	-

Meagher County City Library

P.O. Box S

White Sulphur Springs, Montana 59645
Phone: (406)547-2250
Email: turtle@mtintouch.net

HB 374 – Construction of New Local Libraries House Appropriations Committee January 30, 2007

Mr. Chairman, members of the committee;

For the record my name is Debbie Benedict and I am the director of the Meagher County City Library in White Sulphur Springs. I am in favor of HB374 and would like to thank Representative French and Senator Kitzenberg for bringing this bill forward.

Our library occupies a 2100 square foot building built in 1979. One-third of our library space is not in use because the floor is sinking. This portion was originally constructed over underground springs in unstable soils. Ceilings in this area leak during heavy snowstorms and rain. We strategically place buckets in certain areas to collect water. Interior walls no longer touch the floor and are suspended only by the ceiling. Two years ago the county commissioners closed this area to the public for safety reasons.

We now have a new leak in the ceiling of our supply room where our main computer server is located. New stress cracks are apparent in various parts of the building. There is insufficient lighting in the non-fiction area. We actually provide a flashlight to patrons who have trouble seeing the spine labels and titles. We have one donated rocking chair, two benches in the front lobby, and one children's table with eight small chairs that provide the only seating for our visitors. We set up a card table with folding chairs for book signings, job service visits, and for other occasions.

Three years ago a portion of the ceiling near the checkout desk fell through during library hours but this was able to be repaired. Past repairs to our closed area have actually caused the floor to sink at a faster rate. Engineering costs to assess our closed area range from \$20,000 to \$90,000. This assessment would only determine if the problem could or could not be fixed. We have reached consensus that remodeling is out of the question. November 2006 we began discussing the feasibility of relocating the library. We have toured available properties but to date none have met our needs. We are also inquiring into possible land parcels. Our county commissioners are involved and support our efforts and I have entered their letter of support into my testimony.

Our library has The Donald W. Johnston Library Trust Fund whose purpose is to assist the library in achieving long-term building and maintenance goals. The fund has \$22,054.03 to date. We do receive monetary contributions each month from our loyal patrons and community organizations. Since September 2006 \$900 has been donated to the library. These monies are being set aside for building needs. Smith River Realty just

announced that our library will be one of four organizations they will be donating to with their 2007 proceeds.

In the past month we received two special book collections. One was from our former newspaper owners Pat and Verle Rademacher who donated their entire history collection to the library. The other was from the family of a White Sulphur Springs resident who donated their mother's book collection. I mention this because these two collections together total 27 boxes of valuable books. Each week our wonderful patrons bring us best-selling books. I have 57 books donated this past week waiting to be catalogued and shelved. The problem is where to put them. We are discarding books but even so face a lack of shelving space. We have added all possible shelving.

Scott Ward, President of Russell Stover Candies visited our library last summer and later donated five computers. As elated as we were with his gift, frustration surfaced in deciding where to place them. Our high school VICA Club is designing and constructing a computer table for us. Once it is finished and the computers set up we will no longer have adequate meeting room space. Our library will soon have nine much needed public computers at the sacrifice of valuable floor space.

Instead of having all of our children together for summer reading program activities this year, we will have groups of 8-10 at one time because of space. In the past we have lined the children on the floor of our hallway to complete crafts because our children's area is crowded with 1-2 feet of walking space between tables and books. Computer users are asked to push in their chairs if we need to access books in back of where they are seated. At the present time 700 adults and children use our library each month and during summer months usage increases to 800 or more. This is amazing considering our entire county population is only 1900. In the past three months we have issued library cards to 38 new patrons. We face a huge challenge.

Our goals for a building are simple. One that provides adequate shelving space for current and future book collections, a children's area large enough to accommodate our youth after school and during activities, a computer room in an area separate from the bookshelves, a community room for various events, and adequate heat, air conditioning, lighting, and seating. I hope I have portrayed to you the challenges we face at our library and why passage of this house bill would mean so much. Thank you so much for this opportunity to present our situation to you.

Respectfully submitted,

Debbie Benedict

Meagher County City Library

15 First Avenue SE

White Sulphur Springs, MT 59645

Library Phone: 406-547-2250

Home Phone: 406-547-2550

Email: turtle@mtintouch.net



Meagher County, Montana

WHITE SULPHUR SPRINGS

OFFICE OF
BOARD OF
COUNTY COMMISSIONERS

January 29, 2007

Mr. Chairman, Members of the Committee I request this letter be entered into the record as a statement of support for HB 374 by the Meagher County Commission.

Meagher County has a city/county library in desperate need of renovation. Our building is literally sinking into the ground. We have consulted engineers, contractors and historians to find a way to correct the structure problem. So far no solution has been found, except to remodel, rebuild or remove the problem area. The county does not have the funds to do any of the above without assistance.

HB 374 sponsored by Representative French and Senator Kitzenberg will assist small libraries with necessary construction, renovation or remodeling costs. The Meagher County Commission strongly urges your support of this legislation.

Our small rural library is a vital part of the community. Every month hundreds of local residents, traveling visitors and area students utilize the facility every minute it is open. People come to read the newspaper, check out a book, do a research project, and use the computers. The library must be remodeled or moved to accommodate this flood of users of all ages, and provide for a safer more productive environment for both staff and the public. Meagher County needs help with either a loan or grant to do the necessary construction or remodeling.

Please support HB 374. For answers to further questions or additional information please contact the Meagher County/City Library at 406-547-2250, or the Meagher County Commission at 406-547-3612 x 2, or Meagher County Commission chair, Jamie Doggett at 406-547-2190.

Thank you for your consideration.

Jamie Doggett, Ckair

Meagher County Commission



PUBLIC LIBRARY

MEACHER

ONE HUNDRED THIRTEENTH YEAR — No. 5 (USPS 336-620)

White Sulphur Springs, Montana 59645

Thursday, January 30, 2003

PRICE 75 CENT

Meagher County/City Library suffers damage to ceilings and meeting room from settling

When librarian Trish Browning experienced falling ceiling recently, she became aware of other building faults of the ibrary. Due to some of those faults, the library has been closed tiles and a lighting fixture in the ions for those who use the Meagher County/City Library until engineers inspect the building for defects and unsafe condi-

Some of those faults go back to earlier problems with the build-

of the building has a three inch The meeting room in the rear drop in the middle of the floor, lying earth that has given problems for some time. The particular area was "mud jacked" in caused by either water or under-1997 to take care of the problem. It has, however, returned,

Baseboards give a true line as fall to the floor as you walk across to where the floor was before the ing the room go from a flat sursettling took place. Those enterface to one that has a noticeable

Looking at the suspended ceil-

ing tile over the sunken spot, you can see brown water spots on er, has said that they can recall some of the tiles. No one, howevwater dripping from the tiles.

ent solutions.

Kyle Harlen, Helena building inspector, used a laser transit to measure the settling that was occurring in the room. The main area undergoing the settling was Fhere was also apparent settling in the center of the meeting room. on some of the foundations, assuming they were level when originally put in.

ing. In addition to the heating there was a small satellite dish weighed down with numerous Harlen used a ladder and found a noticeable sag in the ceiland air conditioning equipment, concrete blocks.


metal foil.

Numbers and measurements from the structural wood I beams were taken to research the loads they were supposed to carry.

the safety of the north meeting mine the ground conditions and tion should be done first to deter-The inspector felt that excava-

He had said to those inspecting

(Continued on Page Two)




Meagher County/City Library, Monday afternoon. The facility becam OTTO OHLSON, Fire Marshal, inspects some of the damage to th dangerous to enter when lights and ceiling fixtures dropped through th ceiling, creating a hazardous situation to users.



LIBRARY CEILING has fallen, showing the plastic covering that was installed when the paper covered insulation was put in when the building was built. It is definitely not up to code and will be replaced.



CEILING LIGHT and debris litter the floor after it had fallen through the ceiling gridwork. The light was never properly installed and was relying on the ceiling tile to hold it in place.



FLOOR in the meeting room has sunk due to shifting of the underlying soils. This baseboard shows a three inch drop from the original level of the concrete floor.